345 Agate St. Broomfield, Colo. 80020 May 27, 1992

Mr. Eric Brinkerhoff Glendale, Utah 84729

Dear Eric:

I spoke with Leon Brinkerhoff, and he is going to have the entrance to the spring cleaned out. The two of you can then determine the flow.

He did not feel that it would be beneficial to bring a ditch in at a lower location on the field. If this was done we would not be able to irrigate the upper part of the field.

We need to have the City of Glendale, replace the water, as is stated in the agreement. If they do not want to do this then they should plug the flowing well, which they are not using. We feel that if you plug the well, the spring will return to its original flow.

Since it has taken so long to reach a decision, we feel that a time limit should be set. We are asking that you come up with a solution by July 1, 1992, concerning this problem.

Sincerely Yours,

H. Barth and Roma Ann Palmer